U) er:

Monday, 12/05/2008 1:21:05 PM

Julie Lecocq

Process Sheet

Customer

: CC-DAR01 Dart Aerospace Ltd.

Sob Number

S.O. No. :

Estimate Number

: 37973 : 10804

P.O. Number

This Issue

: 12/05/2008

Prsht Rev. First Issue

: NC

: 13/03/2008 Type

: 00015

Previous Run

Written By Checked & Approved By

Comment

: SKIDTUBES

Drawing Name

: D412-742-013

Part Number

: D412742013 · RTN08-013

Drawing Number Project Number

Drawing Revision

Material

: 20/03/2008 Due Date

2 Um:

Each

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

INSPECT WORK TO CURRENT STEP

1.0

QC5

Comment: INSPECT WORK TO CURRENT STEP

-2.0

3.0

D412742013

Float Skidtube Installation

Comment: Qty.:

1.0000 Each(s)/Unit

Total:

2.0000 Each(s)

Float Skidtube Instln

Qty 1 D412-742-013 original B30363 @ CHG003

Qty 1 D412-742-013 original B31709 @ CHG003

HAND FINISHING RESOURCE #1







Comment: HAND FINISHING RESOURCE #1 1- Disassemble all hardware. 2- Keep, and identify the following:

> -1x D2571 saddle B 30090 -1x D2572 saddle B 30543

-1x D2573 saddle B 30594

-1x D2574 saddle B 30 595 -2x D2876 spacer B 78 016

-2x D2877 spacer B 30055

-16x D3403-1 bushings B 31712 -8x D3403-3 bushings B 30343

-1x D3405-041 GH lug B 2631 4 -1x D3405-043 GH lug B 26 315

-1x D8407-041 tow ring B 3039 V Discard all hardware.

**** see original w/o, D412-742-013 B30363 for B#'s ****

1257 (saddle A 3 Ned 7 -1025725Addle A B31714 -D25734/1332167 D2574 SAEdle AB31718/1331722 1025734/B31712V

08-08-15

Dart Aerospace Ltd

W/O:		WORK ORDER CHAN	IGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC-Inspector
08-06-	3.1	Replodine saddles / 4x Lugs } Repowder COAT WHITE		08/06/16	8 12	(Descur)	odule
8-06	3.2	Q.C.3 INPECT powden coata (Wemica) convention	H	08/04/16	12	1000618	orloal 18

Part No: _	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
			QA: N/C Closed:	Date:

NCR:		- 5-47	WORK ORDI	ER NON-CONFORMANC	E (NCR)			
		Description of NC		Corrective Action Section B		Verification	Annroval	Anneoval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspecto
							÷	
	-		9.					
		·						
							····	
٠		ì,						

Monday, 12/05/2008 1:21:05 PM Date: Julie Lecocq User: **Process Sheet Drawing Name: D412-742-013** Customer: CC-DAR01 Dart Aerospace Ltd. **Part Number:** D412742013 Job Number: 37973 Job Number: Seq. #: Description: Machine Or Operation: HAND FINISHING1 HAND FINISHING RESOURCE #1 4.0 Comment: HAND FINISHING RESOURCE #1 Disassemble and identify the following: 1 => D 34 07-041 13 30394 -1x D3564-5 B 3 2054 -1x D3391-023 B 3 1 848 1=) 0346 1-041 1331346 -1x D3391-025 B 31446 -1x D3391-021 B 36925 -1x D3564-1 B 3 1417 AII -1x D3564-3 B 3 1419 PISCARTED discard all hardware, and give the D3566 gaskets to Jason.M. _____ JJ **** see original w/o D412-742-043 B32123 for B#'s **** HAND FINISHING RESOURCE #1 5.0 HAND FINISHING1 Comment: HAND FINISHING RESOURCE #1 - Remove all Silver paint from all the parts. - Try Hot preassure wash to remove silver paint on the tube it self. Employee Labour Cost Adjustment EMP COST ADJ 6.0 Comment: Sub-Contracting Employee Labour Cost-Adjustment POWDER COATING 7.0 M107550 Comment: POWDER COATING Powdercoat white per QSI005 8.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION HAND FINISHING RESOURCE #1 9.0 Comment: HAND FINISHING RESOURCE #1 Pick the following to assemble:

Dart Ae	rospace	e Ltd							
W/O:			WC	RK ORDER CHANGI	ES				
DATE	STEP	PR	OCEDURE CHAI	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·							
				·· ·					
	-								
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	No DQ	A:	Date:	
		·			QA: N	I/C Close	d:	_ Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NC	₹)			
		Description of NC		Corrective Action Section	on B	Vorifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Sect	ion C	Chief Eng	QC Inspector
		ヘ.			-				
							:		

		Description of NC		Corrective Action Section B		Verification	Annroyal	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
		~						
						·:		

Date: Monday, 12/05/2008 1:21:05 PM User: Julie Lecocq **Process Sheet Drawing Name:** D412-742-013 Customer: CC-DAR01 Dart Aerospace Ltd. Part Number: D412742013 Job Number: 37973 Job Number: Description: Seq. #: Machine Or Operation: INSERT 10.0 NAS1330S3KB166 Total: 2.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit **INSERT** 11.0 Comment: PACKAGING RE Identify and pack for shipping as per PPP D412-742-043 Location PPP Rev FINAL INSPECTION/W/O RELEASE QC21 12.0 Comment: FINAL INSPE Gasket 13.0 D35661 2.0000 Each(s)/Unit Total: 4.0000 Each(s) Comment: Qty.: **GASKET** Gasket 14.0 D35665 Comment: Qty.: 1.0000 Each(s)/Unit Total: 2.0000 Each(s) **GASKET** ړلو BOLT 15.0 AN3C4A Comment: Qty.: 24.0000 Each(s)/Unit Total: 48.0000 Each(s) **BOLT** 911 Batch BOLT AN3C6A 16.0 12.0000 Each(s)/Unit Total: 24.0000 Each(s) Comment: Qty.: **BOLT** M 105300 08-05-13 Batch:_

Dart Aerospace Ltd

W/O:	·	WORK ORDER CH	IANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
-	10.1	Install inserts As per along.	A.	80° H	(2)	108-05-13	680513
	10.2	QC5 Insert inspection.		oblosty	æ	1020513	108-05-13

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
			QA: N/C	Closed:	Date:

NCR:	WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section B		Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspecto
		·						
•								

Date: Monday, 12/05/2008 1:21:05 PM User: Julie Lecocq **Process Sheet Drawing Name: D412-742-013** Customer: CC-DAR01 Dart Aerospace Ltd. Part Number: D412742013 Job Number: 37973 Job Number: Seq. #: Description: **Machine Or Operation: BOLT** 17.0 AN3C7A Comment: Qty.: 8.0000 Each(s)/Unit Total: 16.0000 Each(s) **BOLT** M167376 Batch: 18.0 washer 88.0000 Each(s) Comment: Qty.: 44.0000 Each(s)/Unit Total: washer Batch: INSPECT WORK TO CURRENT STEP QC5 19.0 Comment: INSPEC WORK TO CURRENT STEP 20.0 D2747 Set Screw 8.0000 Each(s) Comment: Qty.: 4.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description Batch 4 D2747 Bolt AN4C6A 21.0 Comment: Qty.: 32.0000 Each(s) 16.0000 Each(s)/Unit Total Pick: **Qty Part Number** Description 16 AN4C6A Bolt AN4C46A 22.0 Comment: Qty.: 4.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: **Qty Part Number** Description 4 AN4C46A Bolt AN4C52A 23.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 16.0000 Each(s) Pick: **Qty Part Number** Description M105423 x 8 AN4C52A Bolt

Dart Aerospace Ltd

W/O:		WORK ORDER CHA	ANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
08 lale 1	20.1	ADD Qty x16 D 3403-1 Bushings B# 36303 x 32	18	08/co/18	32	Joseph	oslades
oxfor/18	20.2	ADD Aty 18 D3403-3 Bashings B2 B37146 x16	18	S/a/8.	16.	POSION	08/05/08

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
			QA: N/C C	losed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
-		Description of NC		Corrective Action Section E		Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
						:	·	
. ,				· · · · · · · · · · · · · · · · · · ·				
					į			

Date: Monday, 12/05/2008 1:21:05 PM User: Julie Lecocq . **Process Sheet Drawing Name:** D412-742-013 Customer: CC-DAR01 Dart Aerospace Ltd. Part Number: D412742013 Job Number: 37973 Job Number: Seq. #: Description: **Machine Or Operation:** AN6C12A **BOLT** 24.0 PW Comment: Qty.: 8.0000 Each(s)/Unit Total: 16.0000 Each(s) Pick: Description **Qty Part Number** Batch 5. 08/16/17 EZ MIOU280 8 AN6C12A Bolt AN960C416L 25.0 Comment: Qty.: 32.0000 Each(s)/Unit Total: 64.0000 Each(s) Pick: Batch 167650 **Qty Part Number** Description 32 AN960C416L ` Washer_ AN960C616L WASHER 26.0 All Same Batch Batch = 16 e end of from Stock please - take out from Stock please 16.0000 Each(s) Comment: Qty.: 8.0000 Each(s)/Unit Total: Pick: Qty Part Number Description 8 AN960C616L Washer 27.0 AN960C716L WASHER 32.0000 Each(s) Comment: Qty.: 16.0000 Each(s)/Unit Total: Pick: Description **Qty Part Number** Washer 16 AN960C716L Nut 28.0 MS210434 29.0000 Each(s)/Unit Total: 58.0000 Each(s) Comment: Qtv.: Pick: Qty Part Number Description MK7285 & 29 MS21043-4Nut 08/66/18 (62)

Dart Aerospace Ltd

W/O:		WORK ORDER CHA	NGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
08/06/18	# 24.1	ADD OLTY KZ D 2876 SADDLE SPACES BA B36275 X 4)85	D/4/18	4	/osiun	08/06/9
osloches	24.2	ADD Qty x2 D2577 SADDLE SPACES. B# B34818 X4	10	Souls	4	Jusiur	S velocke

Part No:	P	PAR #: F	Fault Category:	NCR: Yes No	DQA:	Date:
				QA: N/C C	losed:	Date:

	·	WORK ORDER NON-CONFORMANCE (NCR)							
	Description of NC		Corrective Action Section B			Approval	Approval		
STEP	STEP Section A		Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector		
-									
	STEP	STEP Description of NC	STEP Description of NC	STEP Description of NC Corrective Action Section B Initial Action Description	STEP Description of NC Section A Initial Action Description Sign &	STEP Description of NC Section A Initial Action Description Sign & Verification Section C	STEP Description of NC Section A Initial Action Description Sign & Verification Section C Chief Eng		

Date: Monday, 12/05/2008 1:21:05 PM User: Julie Lecocq **Process Sheet Drawing Name:** D412-742-013 Customer: CC-DAR01 Dart Aerospace Ltd. . ★ Job Number: 37973 Part Number: D412742013 Job Number: Seq. #: Description: Machine Or Operation: NAS1515H4L WASHER 29.0 Total: 64.0000 Each(s) Comment: Qty.: 32.0000 Each(s)/Unit Pick: Batch 10 7008 Description **Qty Part Number** 32 NAS1515H4L Washer WASHER 30.0 NAS1515H6L Comment: Qty.: 8.0000 Each(s)/Unit Total: 16.0000 Each(s) Pick: **Qty Part Number** Description Batch M18918 8 NAS1515H6L Washer 8/06/18(12) 31.0 NAS1515H7L WASHER Comment: Qty.: 32.0000 Each(s) 16.0000 Each(s)/Unit Total: Pick: Batch **Qty Part Number** Description M100727 16 NAS1515H7L Washer D34173 Washer 32.0 Comment: Qty... 2.0000 Each(s)/Unit Total: 4.0000 Each(s) Pick: **Qty Part Number** Description D3417-3 WASHER 2 33.0 D34561 Comment: Qty.: 1.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: Batch **Qty Part Number** Description D3456-1 WASHER

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mg) Approval QC Inspector				
osladie	29.1	ADD QH &1 D 8407-041 Tow Ring BB B35780	18	સ્ત્રીલ/18	×a	/ws1042 08/06/				
OSlow	1292 V	A Soblochs								

Part No:	PAR #:	Fault Category:	NCR: Yes	No	DQA:	Date: _	
			QA: N	1/C C	losed:	Date:	

	WORK ORDER NON-CONFORMANCE (NCR)								
	Description of NC Corrective Action Section B			Varification Annual	Approval	al Approval			
STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector		
					I				
							:		
	STEP	STEP Description of NC	STEP Description of NC Section A Initial	STEP Description of NC Section A Initial Action Description	STEP Description of NC Section A Initial Action Description Sign &	STEP Description of NC Section A Initial Action Description Sign & Section C	STEP Description of NC Section A Initial Action Description Sign & Verification Section C Chief Eng		

Date: Mon	day, 12/05/2008 1:21:05	PM	•					1
User: Julie	e Lecocq		Process Sh	eet	•			
• Customer:	CC-DAR01 Dart Aeros	space Ltd.	Drawi	ng Name: D412-74	42-013			
Job Number:	37973		Pari	Number: D41274	2013			
Job Number:					· · · · · · · · · · · · · · · · · · ·			
Seq. #:	Machine Or Operation	1:		Description	ı:			,
34.0	AN4C7A		Bolt					
Comme	•	ch(s)/Unit Total	: 8.0000 Each(s)		1			
>	Bolt Batch:	M106302			\mathcal{N}	0/80	6/18	(X)
35.0	QC4		INSPECT 100% KIT	S FOR COMPLETED	NESS		1, .)
. ,			/08U	218/1				
	ent: INSPECT 100% KI	TS FOR COMPLE		5 Prolinge	ed in box	<u> </u>		
36.0	PACKAGING 1		✓ ACKAGING RESO	URCE #1				
Comme		OURCE #1	- com	House				
Comme		•	vith the new batch #@	HG003				
	Identify and pack for	or shipping as per f	PPP D412-742-013					
	Location:	$-\rho_{a}$	-		IX al	Palic		(3)
37.0	PPP Rev:	<u> </u>	FINAL INSPECTION	I/W/O RELEASE	<u> </u>	<u>106/18</u>		
·						08	2/07/0) A
Comme	IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII				110001100000101000	(IIII) IIII	· // -	
Job Completion		- 				MF	08-0	6-30
						,		
							•	
			·					
								,

Dart Aerospace Ltd

W /O:		WORK ORDER CHANGES	WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
Dort No	_	DAD # Fault Catamanu NC	D . V	No DO		Deter	I				

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
			QA: N/C	losed:	Date:

NCR:			WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section B			Approval Chief Eng	Approval QC Inspector		
DATE STEP		Section A	Initial Action Description Chief Eng Chief Eng		Sign & Date	Verification Section C				
					·					

Tuesday, 18/03/2008 9:05:53 AM User: Linda Lacelle **Process Sheet** Customer **Drawing Name** : D412-742-013 : CC-DAR01 Dart Aerospace Ltd. Job Number : 37973 **Estimate Number** : 10804 : D412742013 P.O. Number Part Number RTN08-013 This Issue : 18/03/2008 S.O. No. : **Drawing Number** Prsht Rev. : NC Project Number : 13/03/2008 : LANDING GEAR First Issue Type **Drawing Revision** : 00015 **Previous Run** Material : 20/03/2008 Qty: 2 Um: Each **Due Date** Written By Checked & Approved By Comment **Additional Product** Job Number: Seq. #: Machine Or Operation: Description: 1.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 2.0 D412742013 Float Skidtube Instin Comment: Qtv... 1.0000 Each(s)/Unit Total: 2.0000 Each(s) Float Skidtube Instln Qty 1 D412-742-013 original B30363 @ CHG003 Qty 1 D412-742-013 original B31709 @ CHG003 3.0 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 B3647x, B30592x1 1- Disassemble all hardware. B 30593 x1, B31714x1 2- Keep, and identify the following: √ -1x D2571 saddle B 5 0 0 B3a167x1, B31717x1 B 31718 XI, B31722X D3574 √-1x D2573 saddle B 3 0 B26314 x2 ∠-1x D2574 saddle B 3 0 D3405-041 ✓-2x D2876 spacer B S B26315 x2 D3405043 √-2x D2877 spacer B 3 00. clad from Storesi √-16x D3403-1 bushings B

3 B35780 X2 ✓-8x D3403-3 bushings B 3 0 3407-041 ♥ -1x D3405-041 GH lug B<u> えらろ</u> D2876 02877 D3403-1 36303 X32 ₹ -√-1x D3407-041 tow ring B ? O **かる403-3** Discard all hardware. **** see original w/o, D412-742-013 B30363 for B#'s

Tuesday, 18/03/2008 9:05:53 AM Date: Geor: Linda Lacelle **Process Sheet Drawing Name:** D412-742-013 Customer: CC-DAR01 Dart Aerospace Ltd. Part Number: D412742013 Job Number: 37973 Job Number: Seq. #: Description: Machine Or Operation: HAND FINISHING HAND FINISHING RESOURCE #1 4.0 Comment: HAND FINISHING RESOURCE #1 Ful B30924 Disassemble and identify the following: 1331843 MiD 30 925 **ጣ**، ሪ -1x D3391-023 B_ B31315 AC+ -1x D3391-025 B € . d -1x D3391-021 B____ ACT B3/3/8 -1x D3564-1 B -1x D3564-3 B R31592 1337973 discard all hardware, and give the D3566 gaskets to Jason.M. 10412 74zer **** see original w/o D412-742-043 B32123 for B#'s **** HAND FINISHING RESOURCE #1 HAND FINISHING1 5.0 68 M107550 Comment: HAND FINISHING RESOURCE #1 Remove all Silver paint from all the parts. — *** 08~04-17(XZ - Try Hot preassure wash to remove silver paint on the tube it self. QUALITY CONTROL QC Comment: QUALITY CONTROL See Jason to complete w/o after the paint is removed. Job Completion Float-Skid-Tubes Rev E Z=> Mid (331843) (B31315) 2x =) Fwd \$ 1330924 830925 EXAFT { 1331318 }

272182142106215481581

B15158 + 576059 + 515158

Date: User: Monday, 12/05/2008 1:21:05 PM

Julie Lecocq

Process Sheet

Customer

: CC-DAR01 Dart Aerospace Ltd.

Job Number

: 37973 : 10804

Estimate Number P.O. Number

This Issue

: NC Prsht Rev.

: 13/03/2008 First Issue Previous Run

: 00015

Written By

Checked & Approved By

Comment

Additional Product

: 12/05/2008 S.O. No. :

Type

: SKIDTUBES

Drawing Number Project Number

Drawing Revision

Drawing Name

Part Number

Material Due Date

: 20/03/2008

Qty:

2 Um:

Each

REFERENCE ONL

: D412-742-013

: D412742013

- RTN08-013

Job Number:



Seq. #:

Machine Or Operation:

Description:

QC5 1.0

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

D412742013

Float Skidtube Installation



Comment: Qty.:

1.0000 Each(s)/Unit

Total:

2.0000 Each(s)

Float Skidtube Instln

Qty 1 D412-742-013 original B30363 @ CHG003

Qty 1 D412-742-013 original B31709 @ CHG003

3.0

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

1- Disassemble all hardware.

2- Keep, and identify the following:

-1x D2571 saddle B_

-1x D2572 saddle B

-1x D2573 saddle B_

-1x D2574 saddle B

-2x D2876 spacer B__

-2x D2877 spacer B_

-16x D3403-1 bushings B_

-8x D3403-3 bushings B_____

-1x D3405-041 GH lug B_____

-1x D3405-043 GH lug B_

-1x D3407-041 tow ring B____

Discard all hardware.


**** see original w/o, D412-742-013 B30363 for B#'s ****


,	londay, 12/05/2008 1:21:05 PM	
User: Ji	ulie Lecocq	Process Sheet
Custome	er: CC-DAR01 Dart Aerospace Ltd.	Drawing Name: D412-742-013
g.a. As	27072	Part Number: D412742013
Job Number:		Fair Maiupel: D4 12145012
JOD NUTIDEL		
Seq. #:	Machine Or Operation:	Description :
34,0	AN4C7A	Bolt Bolt
0	mont: Ot 1 4 0000 Tool (a) // limit	Total: 9 0000 Each(s)
Com	ment: Qty.: 4.0000 Each(s)/Unit Bolt	
	Batch:	REFERENCE ONLY
35.0	QC4	INSPECT 100% KITS FOR COMPLETENESS
Com	ment: INSPECT 100% KITS FOR C	
36.0	PACKAGING 1	PACKAGING RESOURCE #1
Com	ment: PACKAGING RESOURCE #	1 70008,5,13
	New labels and paperwork re	equired with the new batch # @ CHG003
	Identify and pack for shipping	
	Location:	y 40 por 111 DTTE 17E 010
	PPP Rev:	FINAL INODESTICINATION OF FACE
37.0	QC21	FINAL INSPECTION/W/O RELEASE
Com	ment: FINAL INSPECTION/W/O RE	ELEASE
Job Completion		
•		
	•	


Form: rprocess


. .


Page 7


















D3391-025 INSERT AND WEARPAD INSTALLATION DETAIL (SEE TABLE)

D3391-015/-025 AFT TUBE ASSEMBLY PARTS LIST

	555 - 010/ 020 /1 1 1000						
QTY - 015	QTY - 025	PART NUMBER	DESCRIPTION				
X		D3391-015	AFT TUBE ASSEMBLY				
- `	X	D3391-025	AFT TUBE ASSEMBLY				
1	1	D6014-090	AFT TUBE				
1	1	D2646	AFT CAP				
1	1	D3537-1	WEARPAD				
1	1	D3537-7	WEARPAD				
1	1	D3553-1	GASKET				
1	1	D3553-3	GASKET				
18	14	NAS1330S3KB366	INSERT (OR AES10KB366)				
4	2 *	NAS1330S3KB316	INSERT (OR NAS1330C3KB316)				
8	6.	NAS1330S3KB266	INSERT (OR NAS1330C3KB266)				
4		NAS1330S3KB216	INSERT (OR NAS1330C3KB216)				
16	12 🗸	NAS1330S3KB166	INSERT (OR NAS1330C3KB166)				
4		NAS1330S4KB151	INSERT (OR NAS1330C4KB151)				
6	6	AN3C4A	BOLT				
4	4	AN3C5A	BOLT				
2	2	NAS1515H3L	WASHER				
10	10	AN960C10L	WASHER				



DRILL 'Q' (Ø0.332-Ø0.338) C'SINK (Ø0.529X100') NAS1330S4KB151 INSERT (1) (4 PLACES)

SECTION U-U
(SCALE 1:3)

AN3C4A BOLT (1)

NAS1515H3L WASHER (1)

AN960C10L WASHER (1)

(2 PLACES)

(1) (1) (1) (1) ES) **DETAIL T** (SCALE 1:3)

OZ.O 7.30 DE CHANGING INSERTS

Per ECN #934

D2646 AFT CAP


- SEAL WITH SIKAFLEX-241/-291

C'SINK AND INSTALL NAS1330S3KBXXX IN HOLES MARKED CS1-CS6 AS FOLLOWS

HOLES MARKED	QTY D3391-015	QTY D3391-025	C'SINK	P/N
CS1	18	14	Ø0.425	NAS1330S3KB366
CS2	4		Ø0.391	NAS1330S3KB366
CS3	4	2	Ø0.391	NAS1330S3KB316
CS4	8	6	Ø0.391	NAS1330S3KB266
CS5	4		Ø0.391	NAS1330S3KB216
·CS6	16	12	Ø0.391	NAS1330S3KB166

	DE
COPYRIGHT © 2005 BY DART AEROSPACE USA, INC.	
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION	C⊦
THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER	DA
PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.	0

.	DESIGN PH	DRAWN BY	DART DART	AEROSPACE USA, INC.
	CHECKED //	APPROVED //	DRAWING NO.	REV. F
		#	D3391	SHEET 5 OF 5
	DATE	<u></u>	TITLE	SCALE
	07.01.18		412 FLOAT SKIDTUBE	1:12



75552-1 03566-13 23553-3 D3564-13 D3560-1 1-28584 4 316 135 166 ah Sold 7 Z 1 565401 25/2 / hatse 1 hsbsal - 98268/ 8428E. 104651 > 6 ans 8 38253, brt 8 0 0488 E 1 R9826 1 HALLE 818701 X18701 38681 33769 X + 2988 K Missing 320

AN3CGA ANAPOCIOL AN3C7A ANBCYA 1246 AN3CSA WASISISH3L 140-1648 88 84 24 107737 * 107376 105300 1 468 tol 107737 68 beal 36216 36184

1. Mid-Tube Assembly PARTS hisT: 1331315 FLOAT-TUDE ASSEMBLY (INSERTS 0~1y) !

NAS 133053 KB 116 TAN NAMO (Q/y: 0

NAS 133053 KB 166 10 SCC75 INSCRTS

Ó

M103954 Stshoi W

BATCH NO:

2, FWD Tube Assembly PARTS hisT: B 3 0925

PACT DAME: NAS 1330 S3KB 166

MY:

BATCHEOS

INSCITS

M103954

3. AFT. Tube Assembly PACTS hisT: 331318

CACT COMC:

三

QTy:

BATCh No:

NAS 133053KB366 INSCETS

M104818 W104818

N

6

M104651

NAS 133053KB 266

INSCETS

M 103954

NAS 133053KBIG6

instal inscrts / 08-05-14 (X)

ac#5 inspect insuts & order/14(FI)

USP A Drop OF Sikafley in each inscrI Holes

LPS SOF Weis 3 MID6094 MID7804 08/10

FloAT-Tube Assembly Parts Lists

·05-14 (XI)	De 18	PLSLQI	(X6) M	P52 E9/W (9X)
	08/10		W10	NAS1515H-31
	MIOTRY CACK Hold	afley in	0	* PUT A 200p
) 1/	556 EOIW		- - 	AN 960-C-10L
Proc All Ast	M107376	0 ;	6 0	AU3C-7A
1 13	M105300	•	12	AN3C-6A
100	78F FOIM		24	AN3CH A
hs	BATCh No:		QTy:	PATTEO:
Αιυ			:(5:	3. Bolts / washers:
	048782 9996571	ì		03553-3
	B38647			P3566 - 5
	1338681		4	123566- 1
)	332744	<u></u> (_	D3566-13
	BATCH NO:		617 ×	PASTNO:
		1		2, GASK ets;
	1333869	ぶ	_	D3537 - 7
	B37749	S	_	13537 - 1
4	333801 B3376	G-	-	D3564-3
336216	1338409	13		D3564-5
(11)14-0101	1333243 D34	13.3	_	13564 - 1
CA	1338253 Tow	133	_	D3564-13
DZ646 (XI) B36184	BATCH NO: DZI	BATO	9Ty:	PACTNO:
TO CAPS.	ΠÍ		wear pads	I. Wear shoes/Wear pads:

FloAT-Tube Assembly (inscrits Only)

I. Mid-Tube Assembly PARTS hist: 1331843 NAS 133053 KB 166 PART NAME: NAS 133053KB116 (insects) (SLUDSCNI) 6 M1039541 BATCH NO: M 1045751 each hole seforce Xuse A prop installing inscrts OF SIKAFIEX IN M10780408/10

2. FWD Tube Assembly Parts List: 1330924 NAS 133053KB 166 PART NAME: (SLADSON) BATCHNO: M103954

YUSCADROP OF SIKAFLEX installing inscrets! in carn Hole before 01180 POBLOIN

3. AFT. Tube Assembly Parts hist; 1331592

NAS 133053 KB 366 PACT NAME: (INSCATS) (in sents) 141. 3

BATCh NO:

*USC Apropsimal

M104818 M104818 before installing IN RACTI MOLE inscrats!

NAS 1330531413316

6

M104651 POStolW GODDAMIT. 08 | 10

NAS 133053 KI3 266 (INDSCRITS)

M1039541

1445 133053K13 166

XLPS & BOTH Sides OF WEB } QC#5 inspect inschooling install inscrits blooms: 140

N 106 096

Float-Tube Assembly Parts hists

I Wearshoes/Wearpads: PARTNO:

MARINO: D3564-13 D3564-1

123564-5

D3564-3

13537 - 7

Z. GASKETS:

PARTNO: D3566-13

D 3566-1

D 3553-1

03553-3

3. Bolts / Washers:

PARTNO: AN3C-4A

AN3C-6A

4103C-7A

AN3C-5A

AN960C-10L

NAS1515H-3L

QTy:

1339286

100

1

1

\

#

//

QTy:

2

1

١

•

1

#

QTY:

24

12

8

4

44

6

batch NO:

B38253 XSAMC

12 3 2 11 2 4

1338409

1333764 1334052

13 37 749

13 338 69

BATCH NO: B32744

338681 Too!

1338647

1222016

1333868

1333870

BATCHNO;

MIO7737 Y PUTA Drop OF

M105300 Sikaflex M107376 M107804

M107737

M107939

M107394

- All FASTURNERS CONTED with Procron LPS M104251

Al 08.05-110

08/10

END CAPS!

PARTNO: D2 1246


1) 34 010:41 (Tow CPP)

30Tchno;

1336216

Skid-Tube! TesT-FiT smeddles on

DART AEROSPACE USA, INC. HEFERENCE ONLY



MDL-D412-742 Page 1 of 1

MASTER DOCUMENT LIST

STATUS	DRAWING #	REV	DESCRIPTION	DATE
R	IIN-D412-742	С	INSTALLATION INSTRUCTIONS	07.01.08
R	ICA-D412-742	2	INSTRUCTIONS FOR CONTINUED AIRWORTHINESS	07.01.08
R	QSI 004	06B	WELDING	06.11.14
R	QSI 005	09A	FINISHING	06.09.14
R	QSI 015	04B	BONDING	06.11.07
R	QSI 018	03B	STANDARD TOLERANCES	06.08.03
		1 1		
N/C	D2500	F1	EXTRUSION	01.04.17
N/C	D2571	E	SADDLE	05.07.13
N/C	D2572	E	SADDLE	05.07.13
N/C	D2573	E	SADDLE	05.07.13
N/C	D2574	E	SADDLE	05.07.13
N/C	D2577	Е	WEARSHOE	00.09.22
R	D2646	С	AFT CAP	06.12.20
N/C	D2747	В	SET SCREW	05.03.09
N/C	D2876	В	SADDLE SPACER	06.06.02
N/C	D2877	В	SADDLE SPACER	06.06.02
N/C	D2913	В	DOUBLER	99.10.18
N/C	D3389	С	412 WEB	06.01.23
R	D3391	F	412 FLOAT SKIDTUBE	07.01.18
N/C	D3401	В	TOW CAP	05.06.09
N/C	D3403	В	BUSHING	06.01.23
N/C	D3404	В	GHW LUG	05.06.14
N/C	D3405	A	GHW LUG ASSEMBLY	05.03.08
N/C	D3407	С	TOW RING	05.09.09
N/C	D3417	C	WASHER	05.06.30
N/C	D3456	Α	WASHER	05.09.01
N/C	D3460	Α	WEARSHOE	05.10.04
N/C	D3499	В	CABLE GUARD	06.08.15
N	D3533	Α.	SET SCREW	06.07.12
N	D3537	В	WEARPAD	07.03.20
N	D3553	Α	GASKET	07.01.11
N	D3564	В	WEARSHOE	07.03.20
N	D3566	Α	GASKET	06.12.18
N	D3591	Α	BUSHING	07.01.16
N/C	D6013	Α	SKIDTUBE MATERIAL	05.03.18
N/C	D6014	Α	SKIDTUBE MATERIAL	05.03.18
N/C	DSI 9319	Α	WEARSHOE INSTALLATION	06.01.09
N/C	DSI 9330	D	CABLE GUARD INSTALLATION	06.08.24
N/C	DSI 9336	Α	BOLT LENGTH CHANGE	06.05.19
N	DSI 9364	В	BUSHING INSTALLATION	07.03.20
N	DSI 9367	Α	D412-742 WEARSHOE KITS	07.02.09

Revision Issue Date		Prepared By	Approved By
Α	05.04.01	PH	DS
В	05.06.21	PH ,	DS
С	05.10.05	PH ❤	DS
D	06.01.27	PH	DS
E	06.04.26	MB	DS
F	06.06.02	MB	DS
G	06.08.24	MB	DS,
Н	07.03.20	PH	-111

Job # 33442

*LEGEND

R = Revised N/C = No Change

N = New

COPYRIGHT © 2006 BY DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: **H**

Date: 07.03.20

Change Record

Part Number D412-742-013
Description FLOAT SKI DTUBE

Page ____ of ____

Chg.	Date	Ву	Relevant Documents
001	05.08.23	10-	PER DR-D412-742 Rev. A
	}		
002	07.01.31	*	DS19364 Rev. A MDL-D412-742 Rev. H
	1	Į	,
003	07.04.17	1994	MOL D412-742 Rev. H, D3391 Rev. F
004	07.1030	+5	D3391 Rev. G. DB670 Rev. A. D3672 Rev. B DR-D412-742 Rov. J. MDL D412-742 Rov. J
		0	DR-D412-742 R.DL D412-142 KW. J
			·
		orms\CHGPEC rowA	Rev A

Friday, 06/04/2007 3:05:14 PM Linda Lacelle ·User: **Process Sheet Drawing Name** : FLOAT SKIDTUBE : CU-DAR001 Dart Helicopters Services Customer Job Number : 31709 : 10366 **Estimate Number** : D412742013 Part Number 414: P.O. Number : UNDER REVIEW **Drawing Number** S.O. No. : NIA : 06/04/2007 This Issue : N/A Project Number Prsht Rev. : NIA : N/A : LANDING GEAR Type **Drawing Revision** First Issue : 13/04/2007 : 30970 Material **Previous Run** Qty: 1 Um: Each **Due Date** Written By Checked & Approved By : Est Rev: A 05.10.13 New Issue KJ/JLM Comment Est Rev:B 06-06-08 As per DSI9336 JLM **Additional Product** Job Number: Description: **Machine Or Operatio** Seq. #: DOCUMENT CONTROL DC 1.0 CHG 003 Comment: DOCUMENT CONTROL Photocopy bluefile and create labels per PPP D412-742-013 FLOAT SKID ASSEMBLY 2.0 Comment: Sub-Component FLOAT SKID ASSEMBLY D412-742-043 B 3.0 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Comment: Qty.: Pick: **Qty Part Number** Description Saddle Fwd Outside 1 D2571 Saddle, Fwd, In 4.0 D2572 Comment: Qty.: 1.0000 Each(s)/Unit Total: Description **Qty Part Number** 1 D2572 Saddle Fwd Inside

. Friday, 06/04/2007 3:05:14 PM Date: Linda Lacelle User: **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Job Number: 31709 Part Number: D412742013 Job Number: Description: Seq. #: **Machine Or Operation:** Saddle, Aft, Out D2573 5.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: **Qty Part Number** Description Saddle Aft Outside 1 D2573 D2574 6.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: Batch Description Qty Part Number Saddle Aft Outside 1 D2574 7.0 D2747 4.0000 Each(s)/Unit Total: 4.0000 Each(s) Comment: Qty.: Pick: **Qty Part Number** Description 4 D2747 D2876 8.0 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Comment: Qty.: Pick: **Qty Part Number** Description 2 D2876 Saddle Spacer 9.0 D2877 Forme dispunde us tal 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Comment: Qty.: Pick: Description **Qty Part Number** 2 D2877 Saddle Spacer Bushing 10.0 D34031 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Comment: Qty.: Pick: **Qty Part Number** 16 D3403-1

Date: Friday, 06/04/2007 3:05:14 PM User: Linda Lacelle **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 31709 Job Number: Description: Seq. #: Machine Or Operation: D34033 11.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: Description **Qty Part Number** Bushing. 8 D3403-3 D3405041 12.0 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Comment: Qty.: Pick: Description **Qty Part Number** 1 D3405-041 **GHW** Lug D3405043 13.0 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Comment: Qty.: Pick: **Qty Part Number** Description GHW Lug 1 D3405-043 AN4C6A 14.0 16.0000 Each(s) Comment: Qty.: 16.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description 16 AN4C6A 15.0 AN4C46A 4.0000 Each(s)/Unit Total: 4.0000 Each(s) Comment: Qty.: Pick: **Qty Part Number** Description 4 AN4C46A AN4C52A 16.0 8.0000 Each(s) Comment: Qty : 8.0000 Each(s)/Unit Total: Pick: **Qty Part Number** Description Bolt 8 AN4C52A

Friday, 06/04/2007 3:05:15 PM Date: User: **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 31709 Job Number: Description: Seq. #: Machine Or Operation: BOLT 17.0 AN6C12A * 7/5/25P 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Comment: Qty.: Pick: **Qty Part Number** Description 8 AN6C12A Bolt AN960C416L 18.0 Comment: Qty.: 32.0000 Each(s)/Unit Total: 32.0000 Each(s) Pick: Description Batch Washer M100 65/ Description Qty Part Number 32 AN960C416L WASHER AN960C616L 19.0 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Comment: Qty.: Pick: Description Batch Washer <u>M/98*22</u> i Description Qty Part Number 8 AN960C616L WASHER AN960C716L 20.0 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Comment: Qty.: Pick: **Qty Part Number** Description 1104093 Washer 16 AN960C716L Nut 21.0 MS210434 29.0000 Each(s)/Unit Total: 29.0000 Each(s) Comment: Qty.: Description Batch /20X M102959 Qty Part Number 29 MS21043-4Nut M100651

Friday, 06/04/2007 3:05:15 PM Date: Linda Lacelle **Process Sheet** User: Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742013 Job Number: 31709 Job Number: Description: Seq. #: Machine Or Operation: Inventory NAS1515H4L 22.0 32.0000 Each(s)/Unit Total: 32.0000 Each(s) Comment: Qty.: Description **Qty Part Number** Washer 32 NAS1515H4L Inventory NAS1515H6L 23.0 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Comment: Qty.: Pick: **Qty Part Number** Washer M1 8 NAS1515H6L Inventory NAS1515H7L 24.0 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Comment: Qty.: Pick: Description **Qty Part Number** 16 NAS1515H7L Tow Ring 25.0 D3407041 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: **Qty Part Number** Description D3407-041 **TOW RING** D34173 26.0 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Comment: Qty.: Pick: Description **Qty Part Number** WASHER D3417-3

Date: . Ušer:

Friday, 06/04/2007 3:05:15 PM

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT SKIDTUBE

Job Number: 31709

Part Number: D412742013

Job Number:



Seq. #:

Machine Or Operation:

Description:

27.0

D34561

washer



Comment: Qty.:

1.0000 Each(s)/Unit Total:

1.0000 Each(s)

Pick:

Qty Part Number

D3456-1

Description WASHER

INSPECT 100% KITS FOR COMPLETENESS

28.0

AN4C7A



Comment: Qty.:

Each(s)/Unit Total: 4.0000 Each(s)

29.0



Comment: INSPEC FOR COMPLETENESS



30.0

PACKAGING 1

Location:



Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-742-013

CHG-003 PH

31.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE



Job Completion



Tuesday, 5/1/2007 8:36:14 AM Kim Johnston **Process Sheet** : FLOAT SKID ASSEMBLY **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer Job Number : 32123 REFERENCE ONLY : 10756 **Estimate Number** : NIA : D412742043 Part Number P.O. Number S.O. No. : 4) D3391 UNDER REVIEW **Drawing Number** : 5/1/2007 This Issue : N/A **Project Number** Prsht Rev. : NC · NA URF 67.05.01 : LANDING GEAR **Drawing Revision** First Issue Type : 31710A Material **Previous Run** Each Due Date 5/8/2007 Qty: 1 Um: Written By Checked & Approved By KJ/JLM Comment ECN 773 dwg @ rev.D EC. Est Rev B 06.02.13 **Additional Product** Job Number: Description: Seq. #: Machine Or Operation: DOCUMENT CONTROL 1.0 Comment: DOCUMENT CONTROL If D412-742-043 is a W/O on it's own, (46003 Photocopy bluefile and create labels per PPP D412-742-043 Wearplate, Centre D25775 2.0 ps.05.01 Comment: Qtv.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) pick: Part Number Description Batch B32054 Weamlate 2577-5 03566-5 Gasket 03564-5 Mid Tube Assembly 3.0 D3391023 Comment: Qty.: 1.0000 Each(s)/Unit. Total: 1.0000 Each(s) pick: Part Number Description D3391-023 Mid Tube Assembly D3391025 Aft Tube Assembly 4.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) pick: Qty Part Number Description D3391-025 Aft Tube Assembly 773391-021

Page 1

Tuesday, 5/1/2007 8:36:14 AM Kim Johnston **Process Sheet Drawing Name: FLOAT SKID ASSEMBLY** Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742043 Job Number: 32123 Job Number: Description: Machine Or Operation: Seq. #: WEARPLATE D34601 5.0 1.0000 Each(s) 1.0000 Each(s)/Unit Total: Comment: Qty.: pick: Part Number Description Qtv Wearplate D3460-1 03564-1 WEARPLATE D34603 6.0 Total: 1.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit pick: 03564-3 Qty Part Number Description Wearplate D3460-3 AN3C4A 7.0 24.0000 Each(s) Comment: Qty.: Total: 24.0000 Each(s)/Unit pick: M103691 Part Number Description Qty 24 AN3C4A Bolt 8.0 AN3C6A 12.0000 Each(s) Comment: Qty.: Total: 12.0000 Each(s)/Unit pick: Description Batch Part Number M103693 Qty **Bolt** AN3C6A 12 BOLT AN3C7A 9.0 8.0000 Each(s) Total: 8.0000 Each(s)/Unit Comment: Qty.: pick: Description Batch Qty Part Number Bolt AN3C7A 8 AN960C10L 10.0 Total: 44.0000 Each(s) 44.0000 Each(s)/Unit Comment: Qty.: pick: M104215 Part Number Description Batch Qty 44 AN960C10L Washer

Comment: PACKAGING RESOURCE #1

Identify and pack for shipping

Identify and pack for shipping as per PPP D412-742-043

Location:____

PPP Rev:_

B 31363

Cerofu SI

Monday, 1/22/2007 7:55:37 AM Kim Johnston **Process Sheet** : FLOAT SKIDTUBE **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer : 30363 Job Number REFERENCE ONLY : 10366 **Estimate Number** : D412742013 Part Number : NIA : UNDER REVIEW 07 01.25 P.O. Number 5.0. No. : 11/1/~ **Drawing Number** : 1/22/2007 This Issue : N/A Project Number : NC Prsht Rev. : N/A LANDING GEAR **Drawing Revision** First Issue :NIA Material : 30362 **Previous Run** Each : 2/15/2007 Qty: 1 Um: **Due Date** Written By Checked & Approved By New Issue KJ/JLM : Est Rev: A 605.10.13 Comment As per DSI9336 JLM Est Rev:B 06-06-08 **Additional Product** Job Number: Description: **Machine Or Operation:** Seq. #: KS 07.0419 DOCUMENT CONTROL 1.0 CHG 003 Comment: DOCUMENT CONTROL Photocopy bluefile and create labels per PPP D412-742-013 &DSI 9330 & DSI 9338 CHG001 FLOAT SKID ASSEMBL 30363A 2.0 Comment: Sub-Component FLOAT SKID ASSEMBLY D412-742-043 B B 3030-57 D2571 3.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: Description: Qty Part Number Saddle Fwd Outside 1 D2571 Saddle, Fwd, In 4.0 D2572 1.0000 Each(s) 1.0000 Each(s)/Unit Total: Comment: Qty.: Pick: **Qty Part Number** Description 1 D2572 Saddle Fwd Inside Saddle, Aft, Out D2573 5.0 1.0000 Each(s) 1.0000 Each(s)/Unit Total: Comment: Qty.:

Batch

Description

Pick:

Page 1

Qty Part Number

Jhnston **Process Sheet Drawing Name: FLOAT SKIDTUBE** f: CU-DAR001 Dart Helicopters Services Part Number: D412742013 **7**mber: 30363 .nber: Description: Seq. #: **Machine Or Operation:** Saddle Aft Outside D2573 Saddle, Aft, In D2574 6.0 1.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Total: Pick: Description **Qty Part Number** Saddle Aft Outside 1 D2574 Set Screw D2747 4.0000 Each(s)/Unit Total: Comment: Qty.: 4.0000 Each(s) Pick: Batch **Qty Part Number Description** 4 D2747 Bolt D2876 8.0 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Comment: Qty.: Pick: Description **Qty Part Number** Saddle Spacer 2 D2876 Saddle Spacer D2877 9.0 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Comment: Qty.: Pick: Description Batch **Qty Part Number** 2 D2877 Saddle Spacer D34031 Bushing 10.0 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Comment: Qty.: Pick: **Qty Part Number** Description 16 D3403-1 Bushing D34033 **Bushing** 11.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) B30353 2X Pick: Batch **Qty Part Number** Description Bushing 8 D3403-3

Page 2

Process Sheet

a: CU-DAR001 Dart Helicopters Services #mber: 30363 nber:

Drawing Name: FLOAT SKIDTUBE

Part Number: D412742013

Seq. #: **Machine Or Operation:** Description:

D3405041 12.0

Lug Assembly

Comment: Qty.:

.0000 Each(s)/Unit

Total:

1.0000 Each(s)

Pick:

Qty Part Number

Batch

1 D3405-041

GHW Lug

Description ¹

D3405043 13.0





Total: 1.0000 Each(s)/Unit

1.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

1 D3405-043

GHW Lug

14.0 AN4C6A





Comment: Qty.:

16.0000 Each(s)/Unit

Total:

16.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

16 AN4C6A

15.0

AN4C46A



4.0000 Each(s)/Unit Total:

4.0000 Each(s)

Pick:

Comment: Qty.:

Comment: Qty.:

Qty Part Number

Description

Batch

4 AN4C46A

Bolt

16.0

AN4C52A







8.0000 Each(s)/Unit Total: 8.0000 Each(s)

Pick:

Qty Part Number

Description in

Batch

8 AN4C52A

17.0

AN6C12A





Comment: Qty.:

8.0000 Each(s)/Unit Total:

8.0000 Each(s)

Pick: **Qty Part Number**

Description 3

Batch

8 AN6C12A

Bolt

, 1/22/2007 7:55:38 AM ohnston

Process Sheet

er: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT SKIDTUBE

#umber: 30363

Part Number: D412742013

.mber:



Seq. #:

Machine Or Operation:

Description:

18.0

AN960C416L

WASHER

Comment: Qty.:

32.0000 Each(s)/Unit Total:

32.0000 Each(s)

Pick:

Qty Part Number 32 AN960C416L Description

Batch

Washer

19.0

AN960C616L

WASHER



Comment: Qty.:

8.0000 Each(s)/Unit Total:

8.0000 Each(s)

Pick:

Qty Part Number 8 AN960C616L Description Washer



20.0

AN960C716L

WASHER



Comment: Qty.:

16.0000 Each(s)/Unit

Total:

16.0000 Each(s)

Pick:

Qty Part Number

Description

16 AN960C716L

21.0

MS210434

Nut





Comment: Qty.:

29.0000 Each(s)/Unit Total:

29.0000 Each(s)

Pick:

Qty Part Number

Description

29 MS21043-4Nut /1/02

22.0

NAS1515H4L

Inventory



Comment: Qty.: 32.0000 Each(s)/Unit Total: 32.0000 Each(s)

Pick: **Qty Part Number** 32 NAS1515H4L

Description Washer

1101428

Process Sheet

er: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT SKIDTUBE

"umber: 30363

Part Number: D412742013

⊿mber:



Seq. #:

Machine Or Operation:

Description:

23.0

NAS1515H6L

Inventory



Comment: Qty.:

8.0000 Each(s)/Unit

Total:

8.0000 Each(s)

Pick:

Qty Part Number 8 NAS1515H6L Description: Washer

Batch

18918

24.0

NAS1515H7L

Inventory



Comment: Qty.:

16.0000 Each(s)/Unit

Total:

16.0000 Each(s)

Pick:

Qty Part Number 16 NAS1515H7L Description

Washer

1100 127

25.0

D3407041

Tow Ring



Comment: Qty.:

1.0000 Each(s)/Unit

Total:

1.0000 Each(s)

Pick:

Qty Part Number

Description

TOW RING D3407-041

26.0 D34173 Washer



2.0000 Each(s)/Unit Total:

2.0000 Each(s)



Comment: Qty.: Pick:

Qty Part Number

Description

Batch

2 D3417-3 WASHER

27.0

D34561



Total: 1.0000 Each(s)/Unit

1.0000 Each(s)

Pick:

Qty Part Number D3456-1

Comment: Qty.:

Description WASHER

Batch

Process Sheet

ner: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT SKIDTUBE

Jumber: 30363

Part Number: D412742013

íumber:



Seq. #:

Machine Or Operation:

Description:

28.0

AN4C7A

Bolt

Comment: Qty.:

4.0000 Each(s)/Unit

Total:

4.0000 Each(s)

Bolt

Batch: 10142

29.0

QC4

CJ07/04/230



Comment: INSPECT 00% KITS FOR COMPLETENESS

30.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

CHG003

67.04.07

QC21 31.0

Comment: FINAL INSPECTION/W/O RELEASE

FINAL INSPECTION/W/O RELEASE



Job Completion



U A. 05-14

Each

Friday, 2/23/2007 1:47:37 PM Kim Johnston **Process Sheet** Draving Name : FWD TUBE ASSEMBLY : CU-DAR001 Dart Helicopters Services Job Number : 30925 REFERENCE ONL **Estimate Number** : 10467 : D3391021 P.O. Number : NIA Part Number D3391 UNDER REVIEW S.O. No. : NA : 2/23/2007 **Drawing Number** This Issue Prsht Rev. Project Number : MACHINED PARTS First Issue Drawing Revision : 30924 Material **Previous Run** : 3/21/2007 Due Date Qty: 1 Um: Written By Checked & Approved By KJ/JLM Comment Est. B 06.02.10 Dwg rev.D ecn 773 EC Est. C 06.05.02 Added inspections EC **Additional Product** Job Number: Machine Or Operation: Description: Seq. #: 1.0 D6013047 SKIDTUBE MAT'L Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) SKIDTUBE MAT'L Pick: Qty Part Number Description Batch Extrusion D6013-047 2.0 LANDING GEAR 1 Comment: LANDING GEAR RESOURCE 1 Cut extrusion to 46.52 +0.010 -0.020 3.0 BENDING BENDING MACHINE Comment: No bender Bend as per Dwg D3391 Using Bend Prog 3391021 4.0 QC5 INSPECT WORK 10 CURRENT STEP

Comment: INSPECT WORK TO CURRENT STEP

HAAS CNC VERTICAL MACHINING #1





Comment: HAAS CNC VERTICAL MACHINING #1

1-Machine as per Folio FA590 Rev. AA & Dwg D3391 Rev.

Identify as D3391-1

2-Deburr

5.0

Friday, 2/23/2007 1:47:37 PM Kim Johnston **Process Sheet** Drawing Name: FWD TUBE ASSEMBLY Justomer: CU-DAR001 Dart Helicopters Services Part Number: D3391021 Job Number: 30925 b Number: Description: Seq. #: Machine Or Operation: INSPECT POWDER COAT/CHEMICAL CONVERSION QC3 13.0 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 14.0000 Each(s) Total: Comment: Qty.: 0000 Each(s)/Unit Pick: Description Qty . Part Number NAS1330C3KB166 Insert 15.0 Comment: HAND FINISHING RESOURCE #1 Install Inserts as per Dwg INSPECT WORK TO CURRENT STEP QC5 16.0 Comment: INSPECT WORK TO CURRENT STEP Tow Cap Assembly D3401041 17.0 1.0000 Each(s) Total: Comment: Qty.: 1.0000 Each(s)/Unit Tow Cap Assembly Pick: B31346 Description Qtv Part Number Tow Cap D3401-041 BOLT 18.0 AN3C4A 4.0000 Each(s) Total: Comment: Qtv.: 4.0000 Each(s)/Unit Bolt Pick: 110369 Description Batch Qtv Part Number AN3C4A Bolt WASHER NAS1515H3L 4.0000 Each(s) Comment: Qty.: 4.0000 Each(s)/Unit Total: M. 1 07/05/03 Washer Pick: Part Number Description Qty

You are logged in...Edit My Profile | Logout

Investors | Careers | Contact Us | Live Help

Friday, May 2

Favorites: Edit Add

Tracking:

Tracking | Expedited Rate Quote | Rate Quote | Bill of Lading | Pickup | Transit Times/Service Maps |

Navigate My Home

- Online Tools
- **Transit Times Information**
- Rates
- Rate Quote
- Expedited Rate Quote
- Rate Quote Review
- Rate Table
- Truckload Rate Quote
- ZIP Lookup
- Bill of Lading/Pickup
- Tracking
- Invoicina
- Document Copies
- Reports
- Claims Resolution
- Forms

Services Coverage/Transit Times Integration Tools

About Yellow Help

Search MyYellow.com



EXPEDITED QUOTE

View Printer-Friendly Page

QUOTE IN U.S. DOLLARS

Quote ID (if calling Customer Service Center)

Exact Express Ground

Canadian Dollars

Use this Exact Express Ground quote to easily GREATERILL OF LADING I PICKUP

\$1,191.78 \$1,241.24

39319894

I want to create a pickup only

SERVICE

Service Days

Guaranteèd Delivery Date (ship by 05/0::/2008)

05/06/2008

3

Your shipment must be ready for pickup by 5 p.m. to qualify for the service days indicated.

Quote Other Yellow Services

Standard Ground Truckload

CHARGE DETAIL

Base Charge 100% Satisfaction Guarantee

Included Proactive Notification Included \$140.00

Value-Added Services BORDER CHARGE US-CAN GROUND \$0.00 OVER DIMS TIER 1 GROUND \$140.00

FUEL SURCHARGE-EE INNET

\$258.58

No

1322

\$793.20

Pricing Days Trade Show Price / GLB 0.6000 Portfolio ID YELL32005 320050 Table of Rates

*Exact Express Ground quotes expire at 5 p.m. on the pickup day. To finalize, click Schedule Pickup Now or call our Customer Service Center at 1-800-610-6500,

> 605/cUois NEW QUOTE

IMPORTANT: When using Exact Express service, please write "Exact Express" on the Bill

Quote generated through the Internet on 05/02/2008

QUOTE REQUEST DETAILS

K6A1K7 Origin

(Served by OTTAWA, ON, CN -

Direct)

70518 Destination (Served by LAFAYETTE, LA -

Direct)

05/02/2008

Requested Pickup

Requested Delivery 05/06/2008 By 5PM

Date

2

Miles 1738

PIECESWEIGHTCLASSLENGTHWIDTHHEIGHT UN/NA 38 97 34 7 420 113 7 7 58 120 4

150

200 Total: 716 lb

Requestor BRIGITTE GOLDEN

6

12


Please note: Yellow provides quote information for your convenience. The quotes below contain information valid at the time of the quote and, as such, may not refler t current service, availability or pricing. If you have questions, please call the Yellow Customer Service Center at 1-800-610-6500.

If a shipment is not identified as a full "Pup" o "Set" at booking but occupies the "full visible capacity" of either a Pup or Set as identified by Yellow Transportation, the shipment will be rated as either a full Pup or full Set plus any overflow. Full visible capacity occurs when one more of the largest pieces in the shipment will not fit on the trailer. Standard, undiscounted Exact Express Pup and Set rates in effect at the time of the shipment will prevail in the case that no customer-specific pricing program is applicab e.

The Exact Express rates quoted here do not apply to shipments to or from trade shows. Please call the Yellow Customer Service Center at 1-800-610-6500, option 4, for Exact Express rates involving trade shows.

My Home | Live Help | Privacy Policy | About Yellow | Help | Site Map | Contact Us

Copyright @ 1994-2008 Yellow Transportation, Inc. All rights reserved.



Friday, 2/23/2007 1:47:38 PM Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FWD TUBE ASSEMBLY

Job Number: 30925

Part Number: D3391021

Jb Number:



Seq. #:

Machine Or Operation:

4

NAS1515H3L

Washer

20.0

AN960C10L

washer

10 PH 07.05.02



A:0000 Each(s)/Unit

Total:

M10421

21.0

HAND FINISHING1

washer

HAND FINISHING RESOURCE #1





Comment: Qty.:



Comment: SMALL & MEDIUM FAB RESOURCE 1 >

22.0

QC5

INSPECT WORK





Identify as D3391-021

Comment: INSPECT WORK TO CURRENT STEP

Install tow Cap as per Dwg D3391

Inspect thread of each insert using DT8821

23.0 PACKAGING 1 PACKAGING RESO JRCE #1



Comment: PACKAGING RESOURCE #1



24.0

QC21

Location:



Identify and Stock

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



W 87-05(1